ROCKY FLATS PLANT EM RADIOLOGICAL GUIDELINES

Manual No.: Procedure No.: 3-21000-OPS-EMRG Table of Contents, Rev 9

1 of 2

Page: Effective Date:

05/31/95

Organization:

Environmental Management

TABLE OF CONTENTS

| | <u>Title</u> | Rev. <u>No.</u> | Effective <u>Date</u> |
|--------------------------|---|--------------------|--------------------------|
| 4-M83-ER-OPS-EMRG-1.0 | Environmental Management Radiological Guidelines for Organization and Responsibilities | 1 | 02/09/95 |
| EMRG 1.1 | Gama Radiation Surveys | 0 | 12/06/91 |
| EMRG 1.2 | Beta RadiationSurveys | 0 | 12/06/91 |
| EMRG 1.3 | Posting of Radiation Protection Requirements | 0 | 12/06/91 |
| EMRG 2.1 | Personnel Contamination Monitoring | 0 | 12/06/91 |
| EMRG 2.2 | Possible Inhalation Exposure | 0 | 12/06/91 |
| EMRG 2.3 | Wounds and Skin Contamination | 0 | 12/06/91 |
| 3-P11-ER-OPS-EMRG-3.1 | Performance of Surface Contamination Surveys | 1 | 05/26/95 |
| •3-B96-ER-OPS-EMRG-03.02 | Survey Requirements for Conditional and Unrestricted Use | 1 | 05/31/95 |
| EMRG 3.5 | Handling of Contaminated Dosimetry/Security Badges | 0 | 12/06/91 |
| EMRG 6.1 | Performance Test and Operational Checks for Ludlum Model 12-A, Model 12, and Model 31 Survey Instruments | 0 | 12/06/91 |
| EMRG 6.3 | Performance Checking and Operation of the Eberline SAC-4 Alpha-Scintillation Smear Counting Instrumentation | 0 | 12/06/91 |
| EMRG 6.4 | Performance Testing and Operation of the Eberline BC-4 Beta Smear Counting Instrumentation | 0 | 12/06/91 |
| EMRG 6.5 | Use of the Bicron Frisk-Tech with the A-100 and B-50 Detectors | 0 | 12/06/91 |

ROCKY FLATS PLANT EM RADIOLOGICAL GUIDELINES

Manual No.: Procedure No.:

3-21000-OPS-EMRG Table of Contents, Rev 9

Page:

2 of 2

Effective Date: Organization:

05/31/95 **Environmental Management**

| | <u>Title</u> | Rev. <u>No.</u> | Effective <u>Date</u> |
|-----------------------|--|--------------------|--------------------------|
| EMRG 6.6 | Use of the Bicron Fidler (Field Instrument for the Detection of Low-EnergyRadiation) | 0 | 12/06/91 |
| | 94-DMR-ERM-0012 | | 01/25/94 |
| 4-P12-ER-OPS-EMRG-6.7 | Performance Checking and Operation of Ludlum Smear Counting Instruments | 0 | 04/07/95 |
| EMRG 9.1 | Respiratory Protection Requirements and Posting | 0 | 12/06/91 |
| EMRG 10.1 | Radiological Deficiency Reporting Program | 0 | 12/06/91 |

Rocky Flats Environmental Technology Site 3-B96-ER-OPS-EMRG-03.02

REVISION 1

RADIOLOGICAL REQUIREMENTS FOR UNRESTRICTED RELEASE

| | anager, nvironmental Operations Management | 1 M.C.B Print Name | YOUSS ARLY | 5-19-95 Date |
|--|--|------------------------|--------------|--------------------------|
| | uality Assurance Program Manager, atta Management and Reporting Services | / S. LUU Print Name | . / . | <u>5 /2 · 95</u> Date |
| DOE RFFO/ER Conc | urrence on file: Yes No V N/ | Α | | |
| Environmental Protection Agency Approval Required: | | | | |
| Responsible Organization: <u>Environmental Restoration Program Division</u> Effective Date: <u>5/31/95</u> | | | | |
| CONCURRENCE BY THE FOLLOWING DISCIPLINES WILL BE DOCUMENTED IN THE PROCEDURE HISTORY FILE: | | | | |
| Data Management and Environmental Opera Radiological Engineer | tions Management | | | |
| | | | | |

USE CATEGORY 3

ORC review not required

The following DMRs have been incorporated in this revision: 95-DMR-000328

This procedure supersedes 4-B96-ER-OPS-EMRG-03.02, Revision 0.

Periodic review frequency: 3 years from the effective date

LIST OF EFFECTIVE PAGES

<u>Pages</u>

Effective Date

Change Number

1-6

5/31/95

95-DMR-000328

TOTAL NUMBER OF PAGES: 6

TABLE OF CONTENTS

| <u>Sec</u> | <u>etion</u> <u>F</u> | Page |
|------------|---|------|
| | TITLE PAGE LIST OF EFFECTIVE PAGES TABLE OF CONTENTS | 2 |
| 1. | PURPOSE | . 4 |
| 2. | SCOPE | . 4 |
| 3. | OVERVIEW | . 4 |
| 4. | PREREQUISITE ACTIONS | 4 |
| 5.1 | INSTRUCTIONS General Laundry and Personnel Protective Equipment | . 5 |
| 6. | RECORDS | 6 |
| 7 | REFERENCES | 6 |

1. PURPOSE

This procedure establishes the survey, control, and documentation requirements for property and waste to be released from areas controlled due to radiological concerns, Radiologically Uncontrolled Areas, and Radioactive Material Management Areas (RMMAs) at the Rocky Flats Environmental Technology Site (Rocky Flats).

2. SCOPE

This procedure specifies the radiological criteria to be used for

- Conditional Release of Property and Waste at Rocky Flats
- Release for Unrestricted Use of Property and Waste from the Rocky Flats.

This procedure applies to Rocky Flats employees and subcontractors.

This procedure addresses the following topics:

- Compliance with Radiological Operations Instructions (ROI)
- Processing laundry and personnel protective equipment (PPE)

This revision is a total rewrite and revision bars are omitted.

This revision supersedes 4-B96-ER-OPS-EMRG-03.02, Revision 0.

3. OVERVIEW

This procedure sets out specific instructions to be followed by subcontractors performing environmental restoration work at Rocky Flats. To avoid duplication and ensure timely implementation of future changes to Department of Energy (DOE) directives, the subcontractor is directed to follow the instructions in the ROI and to substitute the subcontractor's personnel titles for those contained in the ROI. Instructions are provided for processing laundry and personal protective equipment (PPE). Subcontractors are authorized to use forms for recording data other than those contained in the ROI where the subcontractor can show that the information gathered is the information required by the ROI.

4. PREREQUISITE ACTIONS

Health and Safety Specialist (HSS)

- Observe the appropriate Limitations and Precautions, Prerequisites, and Instructions in 4–S23–ROI–03.02, Radiological Requirements for Unrestricted Release. If questions arise concerning technical instructions and guidelines in the ROI, resolve them with the Environmental Restoration Radiological Engineer (ERRE).
- [3] Brief all personnel on the contents of 4–S23–ROI–03.02. Emphasize that the ROI refers to performers by unique titles and that the following equivalent titles apply.

Radiological Operations (RO) Supervision

=> Environmental Restoration Radiological Engineering (RE)

Radiological Control Technician (RCT)

=> Health and Safety Specialist (HSS)

5. INSTRUCTIONS

5.1 General

HSS

Perform all tasks required by 4–S23–ROI–03.02 in accordance with the instructions contained in 4–S23–ROI–03.02. Where forms are required by the ROI, subcontractors may substitute other forms if all information required by the ROI is captured on the subcontractor's form.

[1] WHEN a situation occurs that is not covered in 4–S23–ROI–03.02, THEN contact Radiological Engineering for guidance.

Radiological Engineering

[2] WHEN guidance is requested by the subcontractor,
THEN provide appropriate guidance in accordance with professional standards, ROIs,
HSPs, DOE standards, and industry standards.

5.2 Laundry and Personnel Protective Equipment

HSS

- [1] Perform surveys of protective clothing and respirators in accordance with 4–167–ROI–02.01, Personnel Contamination Monitoring.
- [2] Document survey results in accordance with 3–P11–ER–OPS–EMRG–03.01, Performance of Surface Contamination Surveys.
- [3] Document results separately on Radiological Contamination Survey Forms.

Site Safety Officer

[4] File completed survey forms in a master survey binder kept in each site Health and Safety Office.

HSS

NOTE Conditional transfer of contaminated items is done in accordance with the ROI.

- [5] IF the protective clothing or respirator is contaminated,
 THEN transfer the item conditionally to the laundry in accordance with the ROI,
 OR store the item in a laundry bag for transfer to the laundry when full.
- [6] WHEN laundry bags are full,
 THEN survey the exterior of the laundry bag in accordance with the 4–167–ROI–02.01.
- [5] IF the protective bag meets the requirements of 4–167–ROI–02.01, THEN transfer the bag conditionally to the laundry in accordance with the ROI.
- [6] Label and handle used disposable PPE in accordance with the ROI.

6. RECORDS

Management of all records is consistent with 1–77000–RM–001, Records Management Guidance for Records Sources.

Environmental Restoration Program Division Records Source

- [1] Ensure that the original and one copy, as required, of the following quality assurance records are transmitted to the Environmental Restoration Program Division Project File Center in accordance with 2–G18–ER–ADM–17.01, Records Capture and Transmittal:
 - Material Transfer and Disposal Form (RF–47555)
 - Property Release Log

Submission of record copies to the Environmental Restoration Program Division Project File Center is in accordance with Administrative Record Requirements, as defined in 2–S65–ER–ADM–17.02, Administrative Record Document Identification and Transmittal.

There are no non–QA records generated by this procedure.

7. REFERENCES

- 1–77000–RM=001, Records Management Guidance for Records Sources
- 2-G18-ER-ADM-17.01, Records Capture and Transmittal
- 2–S65–ER-ADM-17.02, Administrative Records Screening and Processing
- 3-P11-ER-OPS-EMRG-03.01, Performance of Surface Contamination Studies
- 4–S23–ROI–03.02, Radiological Requirements For Unrestricted Release
- 4-I67-ROI-02.01, Personnel Contamination Monitoring